DART SERVICE INSTRUCTION

TO AMEND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D205-634 REV. 0 OR LATER & ICA-D204-635 REV. 0 OR LATER

REF. CANADIAN STC: SH96-88 REF. FAA STC: SR00563NY


AND MAINTENANCE MANUAL SUPPLEMENT MMS-D209-669 REV. A OR LATER AND INSTALLATION INSTRUCTIONS IIN-D209-669 REV. B OR LATER

For the D205-634-XXX or D204-635-XXX or D209-669-XXX skidtube installation, tow ring holes that have become enlarged can be repaired using two D3673-1 Bushings as follows:

- 1) Remove the D2968-041/D3407-041 Tow Ring and associated hardware from the skidtube. Clean the area of paint, etc.
- 2) Drill out the tow ring mounting holes on both the inboard and outboard sides of the skidtube to Ø0.875" +0.006" Deburr the holes and touch up the finish per ICA-D205-634 or ICA-D204-635 or MMS-D209-669 as applicable.
- 3) Install the D3673-1 Bushings into each hole (2 places) using Sikaflex -241/-291 or Proseal 890 or MIL-S-8802 Class B2 sealant as shown below. Note that it is acceptable to reduce the length and/or cap thickness of the bushings as required.
- 4) Re-install the tow ring per ICA-D205-634 or ICA-D204-635 or IIN-D209-669 as applicable.

PARTS LIST

QTY -011	PART NUMBER	DESCRIPTION
X	DSI 9387-011	TOW RING HOLE REPAIR KIT
2	D3673-1	BUSHING





В	ADDED XXX-D209-669 REV. X TO AMENDED DOC LIST				11.06.23
Α	NEW ISSUE			LE	07.10.01
REV.		, [DESCRIPTION	BY	DATE
DESIGN (=		Œ	DART AEROSPACE LTD		
DRAWN			HAWKESBURY, ONTAR		
CHECKED		W	DRAWING NO.		REV. B
MFG. APPR.		N/A	DSI 9387 SHEET 1 O		
APPRO\	VED		TITLE		SCALE
DE APPR.			SKIDTUBE TOW RING HOLE REPAIR NTS		
DATE	11.00	6.23	COPYRIGHT © 2007 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.		